

TV Inspection with Pipe-Run Graph

| | | | |
|---|-----------------------------------|---------------------------|--------------------------------------|
| Project Name: 1st Ave North | Asset ID: YT 32 to 45 | City: Your town | Address: 145 S Main Street |
| Pipe Width: 8 | Pipe Height: 8 | Pipe Type: Clay | Surface Condition: Asphalt |
| Direction: Towards Downstream | Surveyed Footage: 370.0 | | |



